L. D. No. 64//

THE HOCKING VALLEY RAILWAY CO.

SECTION FOREMAN'S

REPORT OF INJURY TO STOCK

Name

Place

Date ___

190

IMPORTANT NOTICE.

The Section Foreman, in all cases of killing of or injury to live stock, will report on this form, to the Supervisor of his section, promptly, all of the facts and particularly the kind and value of the stock killed or injured, where and how the stock got upon the track; if through fences or across cattle guards their condition immediately before the stock was killed or injured; together with any other information of interest, and a pencil sketch on the back of this report, when that will make plainer the facts contained in it.

Etiel when the me fine of the Carly was truled

HOCKING VALLEY RAILWAY CO.

SECTION FOREMAN'S Report of Stock Killed or Injured.

Drive Stratoville onia Rehly 1909
TO THE ENGINEER MAINTENANCE OF WAY, Columbus, Obio
DEAR SIR:
The following live-stock, belonging to the person named below, was
section, viz.:
1. Number any kind of stock killed, or if injured, extent of injury.
Leaven Arillan (Arian)
2. Value of each down Janesky
4. Residence Lieur Straitsville Ohio
5. Date of Accident 9/18 190 9 Time it occured 6 M
6. Place:—Name of and distance to nearest station Ordel Krulle north of Strauburt
7. No. of nearest telegraph pole 07-3
8. Where and how did they get on the right of way?
dence in and androny
9. If through a farm or private gate, what was its condition?
10. If gate was open, how long had it been?
11. Kind and condition of fences and cattle guards, where stock got upon right of way find or fence or
12. Were they allowed by the owner to run at large?
13. What disposition was made of them, and by whom? Berried by Rection onen
14. No. of Train 234 No. of Engine 64
15. Names and residence of those who can give any information connected with the matter do not know
of any one that can give any information
16. Remarks:
To. Remarks.
OB Cherring Foreman, Section No. 48
Correct & Please Supervisor, Dist. No. 4
9-05—1M. Pads. 47699

THE HOCKING VALLEY RAILWAY CO.

ENGINEMEN'S

REPORT OF INJURY TO STOCK

Instructions to Enginemen:

In all cases of killing of or injury to horses, cattle, sheep or hogs by your train, you are required to furnish all the information in your power, as noted below. Fill up one of these blanks in ink and forward to the Master Mechanic, COLUMBUS, O., at the end of trip after the accident. This report should be made as full as possible, and embody every fact that may be of interest to the Company. Send a separate report for each accident.

N. Parket	
1.	Date, Slift 18-1909 .
2.	Time of day or night, 6 P. m night
3.	Place. State locality, distance to nearest station, and number of nearest telegraph pole, one Mile North
	of Straitwille Station
4.	Train No. 234 .
5.	Engine No. 64
6.	Whistle sounded or not, Whistle Sounded
7.	
8.	Brakes applied or not, 1100
9.	Train checked or not, Mex
0.	Engine reversed or not, Wo
1.	
2.	Rate of speed, 25 Miles her Hours
3.	
	Wet or dry rail, Number and kind of animals Office of the state of t
4.	Number and kind of animals, one Calf
5.	Extent of injury to stock, Killed
6.	Extent of injury to engine or train, Novel
7.	On road crossing or not, not on road Crossing
8.	Was road fenced at place where stock came upon right of way, not fenced
9.	Remarks,
	The all and we treat a man the ensure that
A	The calf lone up on track so near the engine that
S	source was to provide source source source

H.S. Leyshon Fireman

THE HOCKING VALLEY RAILWAY CO.

H. EOSPEAKS,



Mr. M. S. Connors,

General Superintendent.

Dear Sir:-

Herewith are regular form reports relative to a calf the property of Dow Tucker being killed one mile north of New Straitsville, September 18th.

Yours truly,

Mouros superintendent.

WO

C. O. H.

OPINION

L. D. No.6411

October 14th,1909.

The reports of Section Foreman and Enginemen show that on September 18th 1909, 6 o'clock P.M., one mile north of Straitsville, pole 61-3, train 234, engine 64, struck and killed a calf, valued at \$7.00, the property of DOW TUCKER.

The train was running about 25 miles an hour on dry rail when enginemen discovered the calf running onto the track about 25 feet ahead of engine. The whistle and bell were sounded, brakes applied and train checked.

The calf got out of enclosure through owner's fence, which was poor, and thence onto right of way were there was no fence.

No liability.

. 37

C. O. H.