


Conrail Schematic Switching Diagrams


for East Columbus, South Columbus,
Heath, Marysville, Kenton, & Findley

Conrail Diagram of **East Columbus** Branch Switching Locations (North of B&O/PRR Panhandle Line)




292 – E. Columbus Industrial Lead	847 – McNally Lumber
839 – Eaton Colby	848 – S. M. Flickinger
841 – Barneby Cheney	849 – S. M. Flickinger
842 – Barneby Cheney	850 – Buckeye Manufacturing
843 – Barneby Cheney	850 – Yenkin Majestic Paint
846 – Blaine Lumber	

Conrail Diagram of the South Columbus Industrial Track Switching Locations




241 – South Columbus Industrial	759 – Owens Illinois
248 – National graphics	760 – Owens Illinois
754 – Columbus Pipe & Equipment	762 – Ajayem Lumber
755 – Columbus Pipe & Equipment	764 – St. Regis Paper
756 – Columbus Pipe & Equipment	

Conrail Diagram of **Heath, Ohio** Switching Points On the former T&OC Eastern Branch




218 – Hebron Industrial	762 – Kaiser Aluminum #2
601 – South Transfer (B&O Interchange)	763 – Kaiser Aluminum #3
602 – Short 8 (B&O Interchange)	764 – Kaiser Aluminum #4
603 – Short 7 (B&O Interchange)	765 – Kaiser Aluminum #5
604 – Fence Track (B&O interchange)	766 – Kaiser Aluminum #6
751 – Byerlyte Long 8	767 – Kaiser Aluminum #7
752 – Byerlyte Long 7	768 – Kaiser Aluminum #8
753 – Byerlyte #1	769 – Kaiser Aluminum
754 – Byerlyte #2	770 – Kaiser Aluminum #9 West
755 – Byerlyte	771 – Kaiser Aluminum #9 East
760 – Kaiser Aluminum Lead	772 – Kaiser Aluminum #10
761 – Kaiser Aluminum #1	

Conrail Schematic Diagram of T&OC Marysville Switching Locations




201 – Western Branch	891 – Team Track (Abandon)
873 – House Track	891 – Marysville Steel
876 – Oil Track	894 – Scotts Farm Seed
877 – Standard Oil	896 - Vacant
880 – Conrad Coal	897 - Vacant
882 – Ohio Grain Elevator	898 - Vacant
885 – Farm Bureau Union County	899 - Vacant
888 – Sohigro	

Conrail Schematic Diagram of **Kenton** Switching Locations



201 – Western Branch	610 – Kenton Yard
203 – stub	794 – Vacant
204 - Algers Running Track	796 – Kenton stub
206 – Algers S.W. Connection	798 – Ohio Farmers
254 – Lead-Kenton Yard	801 - Vacant
602 – Kenton Yard	802 - Vacant
603 – Kenton Yard	803 - Vacant
604 – Kenton Yard	813 – stub
605 – Kenton Yard	835 – Landmark Storage
606 – Kenton Yard	836 – Landmark
607 – Kenton Yard	837 – Landmark
608 – Kenton Yard	840 – Morton Buildings
609 – Kenton Yard	

Conrail Diagram of **Findlay** Switching Locations
 (note - Whirlpool is the northern
 most facility on this drawing)



201 – Western Branch	744 – Whirlpool Storage
238 – Lead – Whirlpool	745 – Whirlpool Storage
241 – Findlay Passing Track	747 – Ball Metal
242 – Runaround Track	749 – DDW Chemical
740 - Whirlpool	750 – DDW Chemical
741 - Whirlpool	753 – W. R. Grace
742 - Whirlpool	756 – Jefco
743 – Whirlpool Storage	757 – Jefco